Belzona Repairs the Clinker Crusher Rotor

ID: 8333

Industry: Mining & Quarrying Customer Location: Cement producer, Slovakia

Application: MPT-Mechanical Power Transmission Application Date: 2020

Substrate: Steel

Products: Belzona® 1111 (Super Metal)

Problem

The crusher rotor was damaged due to the loading and working environment.









Photograph Descriptions

- 1. Damaged rotor
- 2. Rotor after machining, preparing for Belzona® 1111 application
- 3. Belzona® 1111 machined
- 4. The rotor prepared for operation

Application Situation

The factory uses this big crusher for fine clinker production.

Application Method

Application was carried out in accordance with Instructions for use. Hand portable lathe was used to machine the rotor.

Belzona Facts

The traditional repair using welding and subsequent grinding of the rotor should take a long time. The repair using Belzona took several days, resulting into significant savings.

